





ES - 108CKR








A01 X1	A02 Long X1	A03 X2	A04 H=3.8MM L=1950MM X1	A05 Long X1	A06 ST3. 5X32 X8	A07 X1
A08 ST3.5X13 X16	A09 X1	A10 X1	A11 M4X20 X1	A12 X1	A13 X1	A14 H=3.8MM L=2100MM X1
A15 M4X20 X2	A16 H=3.8MM L=1950MM X2	A17 M4X14 X14	A18 X2	A19 X4	A20 X1	A21 X1
A22 X1	A23 X1	A24 X1	A25 X1	A26 M4X20 X3	A27 Short X1	A28 ST3. 5X10 X2
A29 X1	A30 ST3. 5X13 X2	A31 X1	A32 ST3. 5X10 X4	A33 ST3. 5X10 X2	A34 Short X1	A35 X1

B01 X1	B02 X1	B03 Short X1	B04 Long X1	B05 X2	B06 X1	B07 X1	B08 X2
B09 X1							


C01 X1	C02 X1
---------------	---------------

A07



X1

A25




X1





2000MM














A25












1100






A07

















A08




ST3. 5X13

X14





$\phi 2.5$



$\phi 5^{+1.0}_{-0.1}$

